

**National Transportation Safety Board  
Washington, DC 20594**

**Brief of Accident**

**Adopted 04/14/2005**

DCA02MA001 File No. 17648	11/12/2001	Belle Harbor, NY	Aircraft Reg No. N14053	Time (Local): 09:16 EST		
Make/Model:	Airbus Industrie / A300B4-605R			Fatal	Serious	Minor/None
Engine Make/Model:	General Electric / CF6		Crew	9	0	0
Aircraft Damage:	Destroyed		Pass	251	0	0
Number of Engines:	2		Other	5	0	0
Operating Certificate(s):	Flag Carrier/Domestic					
Name of Carrier:	AMERICAN AIRLINES INC					
Type of Flight Operation:	Scheduled; International; Passenger Only					
Reg. Flight Conducted Under:	Part 121: Air Carrier					
Last Depart. Point: New York City, NY			Condition of Light: Day			
Destination: Santo Domingo			Weather Info Src: Weather Observation Facility			
Airport Proximity: Off Airport/Airstrip			Basic Weather: Visual Conditions			
			Lowest Ceiling: None			
			Visibility: 10.00 SM			
			Wind Dir/Speed: 270 / 008 Kts			
			Temperature (°C): 6			
			Precip/Obscuration: None / None			
Pilot-in-Command	Age: 42		Flight Time (Hours)			
Certificate(s)/Rating(s)			Total All Aircraft: 8050			
Airline Transport; Multi-engine Land			Last 90 Days: 146			
Instrument Ratings			Total Make/Model: Unk/Nr			
Airplane			Total Instrument Time: UnK/Nr			

The Board's full report is available at <http://www.nts.gov/publictn/publictn.htm>.

On November 12, 2001, about 0916:15 eastern standard time, American Airlines flight 587, an Airbus Industrie A300-605R, N14053, crashed into a residential area of Belle Harbor, New York, shortly after takeoff from John F. Kennedy International Airport, Jamaica, New York. Flight 587 was a regularly scheduled passenger flight to Las Americas International Airport, Santo Domingo, Dominican Republic, with 2 flight crewmembers, 7 flight attendants, and 251 passengers aboard the airplane. The airplane's vertical stabilizer and rudder separated in flight and were found in Jamaica Bay, about 1 mile north of the main wreckage site. The airplane's engines subsequently separated in flight and were found several blocks north and east of the main wreckage site. All 260 people aboard the airplane and 5 people on the ground were killed, and the airplane was destroyed by impact forces and a postcrash fire. Flight 587 was operating under the provisions of 14 Code of Federal Regulations Part 121 on an instrument flight rules flight plan. Visual meteorological conditions prevailed at the time of the accident.

Brief of Accident (Continued)

DCA02MA001				
File No. 17648	11/12/2001	Belle Harbor, NY	Aircraft Reg No. N14053	Time (Local): 09:16 EST

---

Occurrence #1: ABRUPT MANEUVER  
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. COMPENSATION FOR WIND CONDITIONS - PERFORMED
2. (F) WEATHER CONDITION - GUSTS

-----

Occurrence #2: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION  
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

3. (C) RUDDER - EXCESSIVE
4. (F) INADEQUATE TRAINING - COMPANY/OPERATOR MANAGEMENT
5. VERTICAL STABILIZER - OVERLOAD
6. VERTICAL STABILIZER - FAILURE
7. (C) VERTICAL STABILIZER - SEPARATION

-----

Occurrence #3: LOSS OF CONTROL - IN FLIGHT  
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

8. AIRCRAFT CONTROL - NOT POSSIBLE

-----

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER  
Phase of Operation: DESCENT - UNCONTROLLED

Findings

9. TERRAIN CONDITION - GROUND

Findings Legend: (C) = Cause, (F) = Factor

---

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.  
the in-flight separation of the vertical stabilizer as a result of the loads beyond ultimate design that were created by the first officer's unnecessary and excessive rudder pedal inputs. Contributing to these rudder pedal inputs were characteristics of the Airbus A300-600 rudder system design and elements of the American Airlines Advanced Aircraft Maneuvering Program.